

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 22 March 2022**

**Australia – Victoria**

**No. 104 - 2022**

**Local Port of Port Phillip**

**Point Wilson**

**Point Wilson Pier Works Exclusion Zone – Lit Special Mark Buoys Reinstated**

**Date:** Immediate

**Previous Notice:** 314(T)-21 is referred and cancelled

**Details:** Mariners are advised that the three missing lit special mark buoys associated with the Point Wilson Pier works exclusion zone, outlined in the table below, have now been reinstated.

Buoy type	Approximate Location (WGS84)	Light Characteristics
Yellow SLB1250 Special Mark	38°05.198'S, 144°30.926'E	Iso2s
Yellow SLB1250 Special Mark	38°05.382'S, 144°31.471'E	Iso2s
Yellow SLB1250 Special Mark	38°05.636'S, 144°32.479'E	Iso2s

All buoys marking the exclusion zone are currently in place.

**Mariners are advised to navigate with caution when within the vicinity of Point Wilson.**

**Charts & Publications**

**Affected:** AUS 157, 143.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please Parks Victoria on 13 1963.**

David Ritman

Manager Regional Planning

Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).