

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 31 May 2021
Australia – Victoria

No. 151(T) - 2021

Local Port of Port Phillip

Portsea
Port Phillip Heads Marine National Park – Portsea Hole - Missing Lit Buoy

Date: Immediate

Details: Mariners are advised of a missing lit special mark buoy, with characteristics Fl.Y.5s, marking the southern boundary of Portsea Hole, at approximate location: 38°18.817'S, 144°42.750'E (WGS84).

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution and within the speed limit within the vicinity of Portsea Hole.

Charts & Publications

Affected: AUS 144, 158

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.