

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 13 December 2019
Australia – Victoria

No. 311 - 2019

Port of Western Port

Watson Inlet

Watson Inlet Channel – Starboard Lateral Mark #1 Pile Removed and Buoy Installed

Date: Immediate

Details: Mariners are advised that the starboard lateral mark pile at approximate location 38° 15.685'S, 145° 15.708'E (WGS84) has been damaged beyond repair and replaced with a starboard lateral buoy at the same location.

Mariners are advised to navigate with caution within Watson Inlet Channel.

Charts & Publications

Affected: AUS 150, 151

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963

Graeme Davis

District Manager, Port Phillip Western Port
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.