

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 04 December 2020
Australia – Victoria

No. 344(T) - 2020

Local Port of Port Phillip

Sorrento
Sorrento Pier Western Lower Landing Fenders

Date: Immediate

Details: Mariners are advised that the berthing fenders on the Sorrento Pier western low landing, at approximate location (WGS84) 38°20.132'S, 144°44.741'E are in poor condition. Mariners should check weather, tides and condition of fenders above and below the waterline for suitability of berthing their vessel at this location.

The fenders will be replaced as soon as practicable.

Mariners are advised to use caution while berthing at Sorrento Pier.

Charts & Publications

Affected: AUS 143, 150, 788

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963

Graeme Davis

District Manager Port Phillip Western Port
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.