

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 1 April 2022
Australia – Victoria

No. 119 – 2022

Local Port of Port Phillip

Beaumaris
Ricketts Point Navigation Piles Repaired

Date: Immediate

Previous Notice: 337(T)-21 is referred and cancelled

Details: Mariners are advised that the damage to several starboard and south cardinal marker piles on the boundary of Ricketts point Marine Sanctuary has been repaired.

The repaired piles are in the following locations:

Description	Locations	Repairs made to:
starboard mark - northern-most pile	37° 59'14"S, 145° 01'02"E	Bent top mark
starboard mark - southern-most pile	37° 59'52"S, 145° 01'46"E	Missing day shape and 5 knot sign damaged
south cardinal mark - south-west corner pile	37° 59'57"S, 145° 02'03"E	Missing 2 lower triangles on the day shape
South cardinal mark – south east corner (Table Rock) pile	37° 59'52"S, 145° 02'18"E	Top mark bent and missing 1 lower triangle

Charts & Publications

Affected: AUS 143, 155

Further Notice: No further notice will be issued

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman
Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.