

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 07 October 2020
Australia – Victoria

No. 286 - 2020

Local Port of Port Phillip

Brighton
Royal Brighton Yacht Club - Buoy #5 Light Reinstated.

Date: **Immediate**

Previous Notice: 280(T) – 2020 is referred and cancelled

Details: Mariners are advised that the Royal Brighton Yacht Club Buoy #5 with characteristics Fl(4).Y.12s situated north of Middle Brighton Harbour, at approximate location 37°53.811'S, 144°58.459'E (WGS84) has been reinstated.

Mariners are advised to navigate with caution when within the vicinity of the buoy.

Charts & Publications

Affected: AUS 143, 155.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.