

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 17 December 2020
Australia – Victoria

No. 357(T) – 2020

Local Port of Port Phillip

Werribee South
Wyndham Harbour Northern Groyne Marker Buoy Missing

Date: Immediate

Details: Mariners are advised that the lit special mark buoy marking the northern groyne at Wyndham Harbour, with characteristics Fl.Y.6s at approximate location 37° 57.849'S, 144° 42.758'E (WGS84) is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Wyndham Harbour.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A Further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.